

REVIEWED
By Anne Nord at 12:58 pm, Mar 02, 2020

3/2/2020


Worklist: 4039

<u>LAB CASE</u>	<u>ITEM</u>	<u>ITEM TYPE</u>	<u>DESCRIPTION</u>
P2020-0498	3	URINE	AM 6 Urine GHB



This method had not been run on this instrument or for at least one year, so a run with the controls was done and checked prior to doing the extraction with the case sample. The data for the controls for both extractions is included. The first extraction was done on 2/28/2020 and the extraction with the case sample was done on 03/02/2020. CS



File :D:\DATA\CDS\2020\GHB 022820 Infrequently Run Method Pre-Run\
... Negative Control.D
Operator : ISP\Datastor
Instrument : Major Mass Spec
Acquired : 28 Feb 2020 11:07 using AcqMethod U-GHB.M
Sample Name: Negative Control - Utak Lot B0130
Misc Info : POC031319



File :D:\DATA\CDS\2020\GHB 022820 Infrequently Run Method Pre-Run\
... Spiked Positive Control.D
Operator : ISP\Datastator
Instrument : Major Mass Spec
Acquired : 28 Feb 2020 10:31 using AcqMethod U-GHB.M
Sample Name: Positive Control
Misc Info : POC031319 + Cerilliant FE08171703



CS

100ug/mL Positive Control




File :D:\DATA\CDS\2020\GHB 022820 Infrequently Run Method Pre-Run\
... Non-Extracted GHB.D
Operator : ISP\Datastor
Instrument : Major Mass Spec
Acquired : 28 Feb 2020 12:04 using AcqMethod U-GHB.M
Sample Name: Non-Extracted GHB
Misc Info : Cerilliant FE08171703

9




File :D:\DATA\CDS\2020\GHB Run 030220 CS\Negative Control.D
Operator : ISP\Datastor
Acquired : 02 Mar 2020 09:34 using AcqMethod U-GHB.M
Instrument : Major Mass Spec
Sample Name: Negative Control - Utak Lot B0130
Misc Info : POC031319
Vial Number: 1





File :D:\DATA\CDS\2020\GHB Run 030220 CS\GHB Spiked Positive Contr
... ol.D
Operator : ISP\Datastor
Instrument : Major Mass Spec
Acquired : 02 Mar 2020 10:02 using AcqMethod U-GHB.M
Sample Name: Positive Control
Misc Info : POC031319 + Cerilliant FE08171703

The vial insert broke during the injection. The sample was transferred to a new insert and vial and reinjected.



File :D:\DATA\CDS\2020\GHB Run 030220 CS\GHB Positive Control-rein
ject.D
Operator : ISP\Datastor
Instrument : Major Mass Spec
Acquired : 02 Mar 2020 12:28 using AcqMethod U-GHB.M
Sample Name: Positive Control
Misc Info : POC031319 + Cerilliant FE08171703

CS



File :D:\DATA\CDS\2020\GHB Run 030220 CS\Non-Extracted RM.D
Operator : ISP\Datastor
Acquired : 02 Mar 2020 12:57 using AcqMethod U-GHB.M
Instrument : Major Mass Spec
Sample Name: Non-Extracted RM
Misc Info : Cerilliant FE08171703
Vial Number: 4

CS

